

**USEPA – Region 6, Dallas, Texas  
Superfund Site Inspection Report  
Hurricane Ike Follow-up**

**\*Site:** Star Lake Canal

**\*Location:** Port Neches, Jefferson County, Texas

**\*Date:** 09/19/08

**\*Remedial Action (RA):** No RA; site in RI.

**\*Site Status:** Site is in remedial investigation; sediment contamination only.

**\*Contacts:** Mr. Peter MacCallan, offsite business/residence. Mr. MacCallan stated that approximately 2.5 feet of mud was in the residence.

**\*Site Conditions:** Appears unchanged.

**\*Comments:** No noticeable change in conditions following hurricane. The adjacent business/residence has storm surge/flood mud within the business area and within the residence; *mud may contain sediment from the canal.*

**\*Recommendation:** no action required.

**\*Pictures:** *Photo#1:* Shot of Star Lake Canal to NE. *Photo#2:* Shot NE; Star lake Canal and adjacent business/residence.

**\*Name:** Charles David Abshire **\*Signature:** \_\_\_\_\_